



# Index

## A

- A-Block.ipt, 293
- Accept, green arrow for, 40
- activating drawing sheets, 175-176
- active constraints, 98, 335
  - displaying, 102
  - hiding, 102
- Active Constraints box, 98-99
- active drawing sheet, 176
- Active Standard command, 173
- adaptive assemblies, 271, 335
- adaptive assembly approach, 19
- adaptive design, 271, 293-295, 335
- Adaptive icon, 294
- Add Trail command, 310
- Adjuster.ipt, 36-37
- adjuster model, 32, 33-42
- A-Horizontal title block, custom, 234
- aligned dimension type, 211
- Aligned solution, of Insert constraint, 283
- alignment in exploded assembly, with assembly modeler, 307
- All option, in extrusion, 71, 89
- ambiguity, in wireframe models, 17
- American National Standards Institute (ANSI), 172, 335
- Angle assembly constraint, 281, 282
- Angle dialog box, 199
- angled work plane, 198-199
- ANSI, 172
  - and leading zeros, 174
  - ANSI A title block, 206, 317
  - ANSI - Large title block, 172, 232, 317
- Application Options, in Tools pull-down menu, 110, 149, 236, 307
- applications, in Inventor, 19
- applying constraints and dimensions, 37-39
- arrays, 231, 335
  - circular, 258
  - polar, 258
  - rectangular, 258, 260
- Arrowheads Inside command, 182
- As Materials drop-down box, on Inventor Standard toolbar, 300
- A-size border, custom, 234
- A-Size-H.idw, 235, 236
- assemblies, exploded, 299-315
- assembly, parametric, 271
- assembly-based fit function, 19, 335
- assembly-centric paradigm, in Inventor, 271
- assembly constraints, 281-283, 335
  - checking, 287
- assembly drawings, 316-334, 335
  - purpose of, 317
- assembly file, 21
- assembly model, editing components in, 292
- assembly modeler, 277, 335
  - to create an exploded assembly, 300, 306
- assembly modeling, 270-298
  - assembly modeling methods, 272
  - Assembly Modeling page, of Visual Syllabus, 26
  - Assembly Panel
    - Constraint command, 283
    - Create Component command, 293
    - Move Component command, 306
    - Place Component command, 278, 290
  - assembly presentation file, 21
  - assembly working drawing, 335
  - associative functionality, 171, 335
    - bidirectional, 271, 292
  - Auto Dimension command, 106, 131-132, 134, 153
  - Auto Dimension dialog box, 131, 134
  - auto dimension feature, 106-107, 336
    - to add dimensions automatically, 107
    - to check existing constraints, 106-107
    - to correct inappropriate dimensions, 134
  - Auto Exploded Assembly.ipn, 308
  - Autodesk, Inc., 16
  - Autodesk Inventor 11, 16, 19
  - Autodesk Inventor Help dialog box, 25, 26
  - automatic constraints, 97
  - automatic exploded view, 307-308, 336
  - Automatic option, in presentation modeler, 307

automatic view creation, 175  
auxiliary plane, 336  
auxiliary view, 194, 336  
    creating, 208  
Auxiliary View command, 208  
Auxiliary View dialog box, 208  
Axis button, in Revolve dialog  
    box, 225  
axis of symmetry, 221, 336

## B

B size, 2 view sheet format, 175,  
    317  
Balloon command, 318  
balloons, 318, 336  
    aligning, 319-320  
base, for press assembly, 300  
base component, 336  
    for assembly model, 277-278  
base feature, 41-42, 63, 336  
    adjusting, 85-86  
    in BORN technique, 148  
    for dryer housing, 248  
    revolving, 249  
Base.ipt, 300, 325-326  
base orphan reference node  
    (BORN) technique, 148-  
    159, 336  
Base Plate.ipt, 275, 278  
base view, 336  
    adding to drawing sheet, 207  
    creating, 177  
    orientation of on drawing  
    sheet, 207  
Base View command, in  
    Drawing Views Panel, 177,  
    207, 236, 317  
Bearing.ipt, 274, 279, 292  
bidirectional associative func-  
    tionality, 271, 292, 337

bill of materials (BOM), 328-  
    329, 337  
    from assembly model,  
    328-329  
    from parts list, 328  
    vs. parts list, 328  
Bill of Materials command, on  
    Tools pull-down menu,  
    328  
Bill of Materials dialog box,  
    328  
binary tree, 60, 337  
    modifying, 60  
    relinking, 60  
    root of, 60  
    terminal branches of, 60  
bisect, 337  
bolt circle, 242, 337  
BOM, 328-329  
BOM Properties dialog box, 318  
Boolean mathematics, 59  
Boolean operations, 59, 337  
Boolean relations, 78, 338  
border, 172  
    defining new, 232-233  
    saving, 233  
Border dialog box, 233  
BORN technique, 148-159, 338  
bottom-up approach to assem-  
    bly modeling, 272, 338  
boundary, 338  
    for trimming or extending,  
    129  
boundary representation  
    (B-rep) method of solid  
    modeling, 18, 338  
branches, of binary tree, 60  
B-rep method of solid model-  
    ing, 18  
buttons, on mouse, 24

## C

C size, 4 view sheet format, 176  
CAD, 16  
CAD Files folder, 27  
CAE, 16  
CAM, 16  
canceling commands, 28  
Cap Screw.ipt, 277  
cap screws, assembling in shaft  
    support, 290  
capturing design intent, 31  
Cartesian coordinate system, 47  
Center\_Drill feature, 160, 163  
Centered Pattern command, 242  
Centerline Bisector command,  
    184, 213, 242  
Centerline command, 214  
centerlines  
    adding to drawing, 184-185,  
    213  
    for circular features, 242  
    editing by dragging, 184-185  
Center Mark command, 184, 212  
center marks, 184-185  
    creating, 212  
center point, 150, 338  
Center point arc command, 155,  
    202  
Center point circle command, 53,  
    67-68, 159, 163, 205  
changing a design, 90-91, 241  
checking assembly constraints,  
    287  
checking constraints, 134-135  
child, 338  
child features, 147  
circle, as construction geometry,  
    229  
circular array, 231, 258  
Circular\_End feature, 85  
circular feature, 223

- circular pattern, 228-231
  - forming, 231
- Circular Pattern command, 231
  - vs. Rectangular Pattern command, 258
- Circular Pattern dialog box, 231, 241
- closing a model file, 28
- CNC machines, 171
- Coil command, 276
- Coincident constraint, 100, 108
- Coincident constraint symbol, 35, 67, 125
- Colinear constraint, 100
- collar, assembling in shaft support, 289
- Collar.ipt, 273, 289
- color, and fully constrained geometry, 102
- Colors tab, of Options dialog box, 307
- Column Chooser button, in Edit Parts List dialog box, 322
- columns and rows, directions in rectangular array, 260
- command descriptions, in status bar, 33
- commands, canceling, 28
- Common Views option, of Rotate command, 45
- component, editing in assembly model, 292
- composite solids, 59, 338
- computer-aided design (CAD), 16
- computer-aided drafting (CAD), 16, 17, 338
- computer-aided engineering (CAE), 16, 338
- computer-aided manufacturing (CAM), 16
- computer-based modeling, 16-18, 338
  - solid models, 18
  - surface models, 18
  - two-dimensional, 17
  - wireframe models, 17
- computer-based processes, 16
- computer database, in 3D wireframe modelers, 17
- computer models, three-dimensional, 16
- computer numerical control (CNC), 338
- computer numerical control (CNC) machines, 171
- concentric, 86, 338
- Concentric constraint, 100
- Concentric constraint symbol, 35
- concentric hole, 86-87
- concurrent engineering, 16, 18, 338
- constrained geometry, color of, 102
- constrained move, 339
- constraining a model, 98-103
- Constraint command, 283, 285, 289, 290, 294
- constraint network, 135, 339
- constraints, 31, 339
  - adding automatically, 107
  - adding manually, 108-109
  - applying, 37-39, 101-103, 283-288
  - assembly, 281-283
  - automatic vs. manual, 97
  - checking, 134-135, 287
  - defaults for, 110
  - and degrees of freedom, 280
  - deleting, 105
  - dimensional, 97
  - displaying, 98-99
  - geometric, 97
  - geometric symbols for, 35-36
  - parametric, 96-120
  - preventing automatic, 35
  - and relations, 97
  - types of geometric, 99-100
- constraint settings, 110
- constraint symbols
  - Coincident, 35, 100, 108, 125
  - Colinear, 100
  - Concentric, 35, 100
  - Equal, 100
  - Fix, 100, 101, 134
  - Horizontal, 35, 100
  - Parallel, 35, 100
  - Perpendicular, 35, 100, 101
  - Smooth, 100
  - Symmetric, 100
  - Tangent, 35, 100, 108, 128
  - Vertical, 35, 100, 102
- construction, geometric, 121-145
- Construction button, on Inventor Standard toolbar, 229
- construction geometry, 228, 339
- construction steps, sequential record of, 78
- constructive solid geometry (CSG), 18, 58-76, 339
  - planning a design with, 61-62
- control variables, 111
- coordinate axes, 42
- coordinate systems, 47-48
  - Cartesian, 47
  - local, 48
  - user, 48
  - world, 47
- coordinate triad, 3D, 23
- Create Component command, in Assembly Panel, 293
- Create Feature command, 293
- Create In-Place Component dialog box, 293

- Create Trails check box, in Select Assembly dialog box, 308
  - Create View command, in Presentation Panel, 307-308
  - creating a drawing file, 172
  - creating a 2D drawing, 172
  - creating engineering drawings, 172
  - crosshairs, 24, 339
  - CSG, 18
    - planning a design with, 61-62
  - CSG binary tree, vs. model history tree, 78
  - CTRL key, to prevent automatic constraints, 35
  - CTRL-], to control visibility of work planes, 199
  - CTRL-S, to save a file, 36
  - curves, 112, 339
  - customizing a parts list, 322
  - cut, 339
  - cut feature, 52, 339
    - cylindrical, 70-71
    - rectangular, 73-74
  - Cut operation, of Extrude command, 59, 71
  - cutting plane, 238, 339
  - cutting-plane line, 238, 339
  - cylindrical cut feature, 70-71
  - cylindrical feature, creating, 67-69
- D**
- database, in 3D wireframe modelers, 17
  - database of file, and CSG, 60
  - datum, 339
  - datum features, 194, 339
    - and auxiliary views, 193-219
  - datum planes, 340
    - with BORN technique, 148
  - decimal places, in dimension format, 64
  - Default Border, for drawing sheet, 232
  - default dimensions, 174
  - default feature names, 85
  - default file names, 81
  - default settings for dimensions, 64
  - default sketch plane, setting, 149
  - Default Standard (ANSI), 173
  - default standards, in Inventor, 173
  - Default tab, of Open dialog box, 20
  - Define New Border command, in Format pull-down menu, 232
  - Define New Title Block command, in Format pull-down menu, 234
  - defining a new border, 232-233
  - defining a new title block, 232, 234
  - defining a part using constraints and relations, 96-120
  - degrees of freedom, 280, 340
    - and constraints, 280
  - Degrees of Freedom command, 280
  - Delete Features dialog box, 163
  - deleting constraints, 105
  - deleting dimensions, 183
  - deleting drawing sheets, 175
  - density of component, 325
  - depth, applying to 2D sketch, 40-41
  - derived dimensions, 114, 340
  - design
    - changing, 90-91, 241
    - computer-aided, 16
    - planning with CSG, 61-62
    - refining with constraints, 37-39
    - design approach, flexible, 165
    - design changes, and associative functionality, 171
    - design characteristics, symmetrical, 221
    - design data, reusing in parametric modeling, 31
    - Design Doctor, 26
    - design intent, 63
      - capturing, 31
      - and constraints, 107
      - and parametric equations, 113-115
    - design process, and parametric modeling, 31
    - designs, flexible, 19
    - design variations, and parametric modeling, 31
    - detail drawing, 340
    - diameter, 340
    - diameter dimensions, 230
    - difference operation, 59
    - dimension, modifying a parent, 161
    - dimensional constraints, 97, 103, 340
    - dimensional values, 112-113, 340
    - dimensional variables, 112-113, 340
    - dimension format, 64, 340
    - dimensioning, 340
    - dimensions
      - adding to part drawing, 211-212
      - applying, 37-39
      - default, 174
      - derived, 114-115
      - displaying, 180-185
      - driven, 104

- hiding, 183
- modifying, 65, 187-189
- modifying in sketches, 40
- reference, 183
- repositioning, 65, 182
- retrieving automatically on
  - part drawings, 236-237
- Dimensions Required box, of
  - Auto Dimension dialog box, 131
- dimension style, 174, 341
- dimension type, aligned, 211
- direct adaptive assembly, 271, 341
- Directed Angle solution, of
  - Angle constraint, 282
- direction, of extrusion, 51
- Direction 1, in rectangular array, 260
- Direction 2, in rectangular array, 260
- displaying constraints, 98-99
- displaying dimensions automatically, 236-237
- displaying feature dimensions, 180-185
- display modes, 46-47
  - hidden-edge display, 46
  - orthographic, 46
  - perspective, 46
  - shaded display, 46
  - using, 47
  - wireframe, 46
- display precision, 111-112
- Document Settings dialog box, 64
  - Units tab of, 111-112
- DOF symbol, 280, 285, 289, 341
- Done, 36, 53
- double-clicking
  - to open a template file, 33
  - to select dimensions, 65
- downstream applications of
  - solid models, 171
- drafting standard, default, 235
- dragging (with mouse)
  - to check assembly constraints, 287
  - to edit a sketch, 126-127
  - to reposition dimensions on a part drawing, 65
- Drawing Annotation Panel, 180, 210
  - Balloon command, 318
  - Centered Pattern command, 242
  - Centerline Bisector command, 184, 213
  - Centerline command, 214
  - Center Mark command, 184, 212
  - General Dimension command, 183
  - Parts List command, 320
  - Text command, 186, 215
- drawing area, 21
- drawing file, 21
  - creating, 172
- drawing files, and templates, 235
- drawing layout, of rod guide, 206-216
- drawing magnification, 24
- drawing mode, 172
  - and history tree, 172
- drawing note, general, 216
- Drawing Resources folder, in
  - history tree, 175, 206, 233, 234, 317
- drawings
  - assembly, 316-334
  - creating, 172
  - scaling, 172
  - and solid models, 171
- Drawings page, of Visual Syllabus, 26
- drawing sheet, completing, 215
- drawing sheet formats
  - B size, 2 view, 175
  - C size, 4 view, 175
- drawing sheets
  - deleting, 175
  - formatting, 173
  - predefined, 175-176
  - working with, 173-177
- Drawing tab, of Options dialog box, 236
- drawing template, 235, 341
  - creating, 235
- drawing view
  - changing scale of, 211
  - setting orientation of, 177
  - setting style of, 177
- Drawing View dialog box, 177, 179, 207, 209, 211, 215, 237
- drawing views, 177
  - adjusting, 211
  - adjusting scale of, 178-179
  - auxiliary, 208
  - base view, 177
  - hierarchy of, 180
  - isometric, 178, 209
  - projected views, 178
  - repositioning, 179-180
- Drawing Views Panel
  - Auxiliary View command, 208
  - Base View command, 177, 207, 236, 317
  - Projected View command, 178
  - Section View command, 238
- Drawn box, in title block, 186
- driven dimensions, 104, 341
- dryer housing, 246-269
  - grill pattern for, 258-261
  - handle for, 250-253
  - modeling strategy for, 247

nozzle for, 254  
shelling, 257  
Dryer Housing.ipt, 264  
dynamic rotation, 44-46  
dynamic UCS, 341  
dynamic viewing functions,  
43-44

## E

edges  
in solid models, 18  
in surface models, 18  
edge view, 341  
Edit Dimension dialog box, 187  
Edit Dimension window, 40, 85  
and parametric equations,  
114  
Edit Feature command, 241  
editing a component in an  
assembly, 292  
editing a parts list, 322-324  
editing by dragging, 126-127,  
341  
editing-by-dragging method,  
126  
and Edit Model Dimension  
command, 188  
editing tools, in 2D Sketch Panel,  
22  
Edit Parts List dialog box, 322  
Edit Sheet command, 206  
Edit Sheet dialog box, 177, 232  
Edit Sketch command, 90, 137  
Edit View command, 211  
to edit drawing views, 179  
e-learning catalog, 26  
ellipse, 341  
engineering  
computer-aided, 16  
concurrent, 18  
engineering design, 16

engineering drawing, 172, 341  
procedure for creating, 172  
English tab, of Open dialog box,  
20, 33  
English units, 20  
ENTER key, and right mouse but-  
ton, 24  
Equal constraint, 100  
equations  
parametric, 114-115  
to refine a design, 31  
errors, fixing with Design Doctor  
and Recover, 26  
ESCAPE key, to cancel com-  
mands, 28  
exaggeration in rough sketches,  
32  
Exercises  
Chapter 2, 56-57  
Chapter 3, 76  
Chapter 4, 93-95  
Chapter 5, 118-120  
Chapter 6, 143-145  
Chapter 7, 167-169  
Chapter 8, 191-192  
Chapter 9, 218-219  
Chapter 10, 245  
Chapter 11, 267-269  
Chapter 12, 297-298  
Chapter 13, 312-315  
Chapter 14, 331-334  
existing constraints  
deleting, 105  
displaying, 98-99  
Exit command, on File pull-  
down menu, 28  
exit marker, for Rotate com-  
mand, 46, 341  
explicit relationship, 147, 341  
exploded assemblies, 299-315,  
342

Explosion Method area, of Select  
Assembly dialog box, 308  
Export Bill of Materials button,  
on Bill of Materials dialog  
box, 329  
Export Parts List dialog box, 328  
Extend command, 129-130  
Extrude command, in Part  
Features panel, 136  
All option, 89  
Cut operation, 71  
Join operation, 68  
To Next option, 89  
Extrude dialog box, 42, 51, 68  
extruding, 40-42, 342  
extrusion  
Cut operation, 52-54  
Join operation, 51-52  
mid-plane, 82, 157  
selecting profile for, 51  
specifying direction of, 51

## F

F1 function key, for help, 25  
F5 function key, to display previ-  
ous view, 43  
F6 function key, to display iso-  
metric view, 43  
F8 function key, to display active  
constraints, 102  
F9 function key, to hide active  
constraints, 102  
face, 41, 342  
feature  
circular, 223  
mirrored, 226-227  
revolved, 221, 225-226  
swept, 262-264  
feature-based modeling, 18-19  
feature-based parametric model-  
ing, 78, 342

- feature control variables, 111, 342
  - feature dimensions, 342
    - displaying, 180-185, 210
    - modifying, 187-189
    - vs. reference dimensions, 183
  - feature names, default, 85
  - Feature Pattern command, 221
  - features, 18, 342
    - child, 147
    - creating using existing features, 78
    - immediate, 160
    - order of, 63
    - order of creation, 61
    - parent, 147
    - placed, 72
    - referenced by other features, 147
    - renaming, 85
    - sketched, 72
    - symmetrical, 220-245
    - underconstraining, 271
  - Features button, in Mirror dialog box, 226
  - feature suppression, 161-165, 342
  - file extensions, for Inventor file types, 20-21
  - file names, default, 81
  - File pull-down menu, 28
    - Save command, 36
  - file setup, using BORN technique, 196
  - files, saving, 27, 36
  - fillet, 90, 133, 249, 342
    - 3D, 256
  - Fillet command
    - in Part Features panel, 252, 256
    - in 2D Sketch Panel, 90, 133, 197, 249, 252
  - Finish Edit command, 292
  - Finish Sketch command, 40, 53
  - finite element analysis, 16
  - first-angle projection, 178, 342
  - Fix constraint, 100, 101, 134
  - flexible design approach, 165
  - flexible designs, 19
  - Flip button, in Extrude dialog box, 69
  - Flush constraint, 288
  - Flush solution, of Mate constraint, 282, 288
  - focal point, in perspective view, 46
  - folder, for CAD files, 27
  - format, for dimensions, 64
  - Format pull-down menu
    - Active Standard command, 173
    - Define New Border command, 232
    - Define New Title Block command, 234
    - Styles Editor command, 173, 210
  - Format Text dialog box, 186
  - formatting a drawing sheet, 173
  - fully constrained geometry, 97, 342
    - and color, 102
  - functions of mouse buttons, 24
- G**
- General Dimension command
    - on Drawing Annotation Panel, 183
    - on 2D Sketch Panel, 38, 40, 153, 224
  - general drawing note, 216, 343
  - general properties of component, 325
  - General tab, of Styles and Standards Editor dialog box, 173
  - geometric constraints, 97, 343
    - applying, 101-103
    - types of, 99-100
  - geometric constraint symbols, 35-36, 343
  - geometric construction, 121-145
  - geometric construction tools, 122, 343
  - geometric definitions, of parametric models, 31
  - geometric entities, 32, 343
  - geometric features, exaggerated in sketch, 32
  - geometry
    - construction, 228
    - fully constrained, 97
    - mirror image of, 221
    - projecting, 200
    - reference, 139
    - solid constructive, 18
  - geometry creation, tools for, 22
  - Getting Started option, of Open dialog box, 20
  - global space, 47
  - graphic objects, manipulating views of, 22
  - graphics window, 23
  - green dot, at key points on features, 67
  - grid, 343
    - for creating new border, 232
    - reference, 23
  - grill pattern, for dryer housing, 258-261
  - grip points, 343
    - on dimensions in part drawings, 212
  - grounded, 343

- grounded component, in assembly model, 279, 280
- guidelines for creating sketches, 32
- guidelines for selecting base feature, 63
- ## H
- half section, 343
- hand cursor, for Pan command, 44
- handle, for press assembly, 304
- Handle.ipt, 304
- helix, 343
- help
- Help Topics command, 25
  - Recover command, 25, 26
  - in status bar, 24
  - Visual Syllabus command, 25, 26
- help options, 25
- Help pull-down menu, 26
- Help Topics icon, 25, 26
- Hidden-Edge Display icon, in Inventor Standard toolbar, 46
- hidden-edge display mode, 46
- hidden features, selecting in Shaded display, 158
- Hidden Line Removed button, in Section View dialog box, 238
- hidden lines, 343
- hiding dimensions, 183
- history, 343
- history-based part modification, 78, 89-91, 343
- history of solid model, tracking, 60
- history tree, 78, 344
- and drawing mode, 172
  - Drawing Resources folder in, 175
- hole
- concentric, 86-87
  - threading at time of hole creation, 301-302
- Hole command, on Part Features panel, 86
- hollowing out a solid model, 257-258
- HOME button on keyboard, 40
- Horizontal constraint, 100
- Horizontal constraint symbol, 35
- housing, dryer, 246-269
- ## I
- .iam file, 21
- icons, 344
- .idw file, 21
- immediate features, 344
- in parent/child relationships, 160
- implicit relationship, 147, 344
- implied parent/child relationships, 154
- inactive drawing sheets, 177
- inappropriate dimensions, correcting with Auto Dimension, 134
- inertial properties of component, 325
- Insert assembly constraint, 281, 283
- inside solution, of Tangent assembly constraint, 283
- interference, 344
- intersect, 344
- Intersect operation, 59
- invalid profile, 122, 344
- Inventor 11, 16
- applications in, 19
  - assembly-centric paradigm in, 271
  - and associative functionality, 171
  - default standards in, 173
  - online support for, 26
  - and part drawings, 171
  - starting, 19
- Inventor Standard toolbar, 21, 22
- As Materials drop-down box, 300
  - Construction button, 229
  - Hidden-Edge Display button, 46
  - Orthographic Camera button, 46
  - Pan button, 43
  - Save button, 235
  - Shaded Display button, 46, 230
  - Sketch button (2D Sketch), 48
  - Undo button, 101
  - Update button, 85-86, 187
  - Wireframe Display button, 46, 198
  - Zoom button, 43
- .ipn file, 21
- iProperties, 325
- .ipt file, 21
- island, 344
- isometric projections, 178, 344
- isometric view, 42-43, 178, 209, 344
- F6 to display, 43
  - shading on part drawings, 215
- ## J
- join, 345
- Join operation, of Extrude command, 59, 68

## L

labels, for section views, 239  
Landscape radio button, in Edit Sheet dialog box, 232  
leading zeros, removing, 174, 210  
left-hand rule of part rotation, 282, 345  
left mouse button, functions of, 24  
length dimension, 38  
line, as construction geometry, 229  
Linear diameter command, 224  
linear diameter dimensions, 224, 345  
linear sweep, 262, 345  
Line command, 33-34  
and status bar, 24  
local coordinate systems (LCS), 48, 345  
location dimensions, for placed features, 72  
Locator.ipt, 66  
locator model, 63-74  
Loft command, on Part Features panel, 247, 250, 253  
Loft dialog box, 253  
lofting, 250-253, 345  
Look At button, 137

## M

machine tool paths, for CNC machines, 171  
magnification, of drawing, 24  
major lines, 345  
manually adding constraints, 108-109  
manufacturing, computer-aided, 16

manufacturing process, and model assembly, 271  
Mate assembly constraint, 281  
material properties, changing, 325  
materials, bill of, 328-329  
Mate solution, of Mate assembly constraint, 281, 290  
methods of assembly modeling, 272  
Metric tab, in Open dialog box, 20, 63  
metric units, 20  
middle mouse button, functions of, 24  
middle-out approach to assembly modeling, 272, 346  
mid-plane extrusion, 82, 346  
midpoint, 346  
midpoint of an edge, highlighted, 67  
minor lines, 346  
Mirror command, on Part Features panel, 221, 226  
Mirror dialog box, 226  
mirrored feature, 226-227, 346  
mirror plane, 227, 346  
Mirror Plane button, in Mirror dialog box, 227  
model  
constraining, 98-103  
starting a new, 20  
Model, in part browser, 23  
Model browser, 21  
model construction, planning, 79  
model construction steps, sequential record of, 78  
Model Example 1.ipt, 28  
model file, closing, 28  
model history tree, 77-95, 346  
vs. CSG binary tree, 78

Drawing Resources folder in, 175  
Sheet Formats folder in, 175  
modeling  
assembly, 270-298  
computer-based, 16  
parametric, 18-19, 30-57  
modeling strategy, 61, 78, 79, 123, 194, 346  
for dryer housing, 247  
and parent/child relationships, 147  
for pulley, 221-222  
model parameters, 346  
models, saving periodically, 227  
modification of part, history-based, 89-91  
modifications  
ease of making, 63  
of parent dimensions, 161  
of sketch dimensions, 40  
mouse buttons, 24  
mouse wheel, functions of, 24  
Move Component command, on Assembly Panel, 300, 306  
Move symbol  
to reposition dimensions, 182  
to reposition drawing views, 179  
multiview drawings, 171, 346

## N

negative side, of 2D surface, 41  
network of constraints, 135  
New File page, of Open dialog box, 20  
New icon, in Open dialog box, 20, 63  
to start a new file, 33  
nodes, in solid models, 18

normal, 346  
of face, 41  
notes, general, 216  
nozzle, for dryer housing, 254

## O

Object Visibility, on View pull-down menu, 199  
offset, 140, 347  
Offset command, in 2D Sketch Panel, 140  
offset cut feature, 140-141  
Offset dialog box, 204  
for Work Plane command, 250  
offset work plane, 204, 347  
online support for Inventor, 26  
Open dialog box, 20, 33  
operations, performing from part browser, 23  
Opposed solution, of Insert assembly constraint, 283  
Options dialog box, 110, 149, 236, 307  
Part tab, 149  
Sketch tab, 110  
order dependency, in part relationships, 19  
order of creation, of features, 61  
order of features in design, 63  
order of parts in parts list, 320, 324  
organizing project files, 27  
Origin, in part browser, 150, 196  
origin, of Cartesian coordinate system, 87, 150, 347  
origin axes, turning on and off, 199  
orphan, 148, 347  
orthogonal, 347  
orthographic camera, 46

Orthographic Camera button, in Inventor Standard toolbar, 46  
orthographic projections, 347  
orthographic view, 46, 347  
orthographic views, 194  
Outside solution, of Tangent assembly constraint, 283  
over-constrained sketch, 104, 347

## P

pan, 24, 347  
Pan command, on Inventor Standard toolbar, 22, 43  
hand cursor for, 44  
Parallel constraint, 100  
Parallel constraint symbol, 35  
parameters, viewing, 115-116  
Parameters command, in 2D Sketch Panel, 115  
Parameters dialog box, 115, 116  
parametric, 18, 347  
parametric assembly, 271, 347  
parametric constraints, 96-120  
parametric definitions, 42  
parametric equations, 114-115, 347  
parametric modeling, 18-19, 30-57, 347  
advantages of, 31  
benefits of, 31  
and design variables, 61  
parametric part modeling, 31-33  
steps in, 31-32  
parametric part modeling process, 31-32  
parametric relations, 97, 111-115, 347  
viewing, 115-116  
parent, 347  
parent/child relationships, 146-169, 348  
in assembly, 281  
examining, 160  
explicit, 147  
implicit, 147  
immediate features in, 160  
implied, 154  
tracking, 147  
parent dimension, modifying, 161  
parent features, 147  
parentheses, for driven dimensions, 104  
part, 348  
editing within assembly model, 292  
part browser, 23, 78, 81, 348  
Model, 81  
Origin folder, 150  
part drawings, 170-192  
part features, renaming, 85  
Part Features panel, 37, 41  
Circular Pattern command, 231  
Extrude command, 136  
Fillet command, 256  
Hole command, 86  
Loft command, 250, 253  
Mirror command, 226  
Revolve command, 225, 249  
Shell command, 257  
Sweep command, 264  
Thread command, 277  
Work Plane command, 198, 204  
part file, 21  
Part Modeling page, of Visual Syllabus, 26  
part modification, history-based, 89-91  
parts, 18

- parts list, 348
  - on assembly drawing, 320-326
  - vs. bill of materials, 328
  - customizing, 322
  - editing, 322-324
  - location of, 320
- Parts List Column Chooser dialog box, 322
- Parts List command, 320
- Parts List dialog box, 320
- Parts List Table Layout dialog box, 324
- Path button
  - in Rectangular Pattern dialog box, 261
  - in Sweep dialog box, 264
- pattern, circular, 228-231
- Pattern command, 228, 231
- pattern leader, 228, 348
  - for rectangular array, 258-259
- permanent exploded assembly, 307
- Perpendicular constraint, 100, 101
- perpendicular constraint symbol, 35
- perspective camera, 46
- perspective view, 46, 348
- Pin icon, 279
- Place Component command on Assembly Panel, 278, 279, 290
- Place Constraint dialog box, 281, 283-287
- placed features, 72, 86-87, 348
- planar faces, 40
- planning a design with CSG, 61-62
- planning for model construction, 79
- planning profile creation, 122-124
- plate, for press assembly, 302
- Plate.ipt, 302
- polar array, 231, 258
- positive side, of 2D surface, 41
- precision, 348
  - of dimensions, 64
  - setting for part drawing, 188
- Precision and Tolerance tab, of Edit Dimension dialog box, 187-188
- predefined drawing sheets, 175-176
- predefined solid primitives, 18
- predictability
  - and constraint network, 135
  - and constraints, 106
  - and degrees of freedom, 280
- presentation background, 307, 348
- presentation modeler, 348
  - Automatic option, 307-308
  - Manual option, 308-311
  - to create an exploded assembly, 300, 307-310
- Presentation Panel, 307
  - Create View command, 307-308
  - Tweak Components command, 308
- Presentations page, of Visual Syllabus, 26
- Press Assembly BOM.xls, 329
- Press Assembly Drawing.idw, 319, 326
- Press Assembly.iam, 305, 307, 325
- press assembly model, 300-305
  - base, 300
  - handle, 304
  - plate, 302
- screw, 303
  - top bar, 301-302
- Press Assembly.xls, 328
- Press Exploded Assembly.ipn, 310, 317, 325
- primitive, 18, 59, 348
- primitive solids, 59, 61, 348
- prismatic solids, 262, 348
- Profile button, in Extrude dialog box, 51
- profile creation, planning, 122-124
- profiles, 122, 348
  - blending, 250
  - introduction to, 122-124
  - invalid, 122
  - refining, 137-139
  - selecting for extrusion, 51
  - sketching, 124-133
- profile sketch approach, to solid modeling, 136, 348
- profile sketches, for lofting, 251
- projected geometry, 200, 349
- Projected View command, on Drawing Views Panel, 178
- projected views, creating, 178, 349
- project files, saving, 27
- Project Geometry command, in 2D Sketch Panel, 155, 159, 163, 197, 200
- projection methods, for part drawings, 178
- Properties dialog box, 325
- pull-down menus
  - File, 28
  - Format, 173
  - Help, 26
  - Tools, 110
- Fulley.idw, 240
- Pulley.ipt, 224, 241

## R

rapid prototyping, 171, 349  
record, sequential, of construction steps, 78  
Rectangle command, 63  
rectangular array, 231, 258, 260, 349  
    direction of rows and columns in, 260  
rectangular cut feature, 73-74  
Rectangular Pattern command,  
    on Part Features panel, 258  
    vs. Circular Pattern command, 258  
Rectangular Pattern dialog box, 260  
    Path button, 261  
rectangular plate.ipt, 116  
Rect\_Cut feature, 88, 160, 163  
reference dimensions, 183, 349  
    vs. feature dimensions, 183  
reference geometry, 139, 349  
    in Inventor part files, 148  
reference grid, 23  
reference planes  
    in Work Plane command, 250  
    visibility of, 187  
references, for work plane, 198-199  
region, 32, 349  
relations  
    and constraints, 97  
    parametric, 97, 111-115  
relationships  
    explicit, 147  
    implicit, 147  
relinking a binary tree, 60  
Remove Faces button, in Shell dialog box, 257  
renaming part features, 85  
repositioning dimensions, 182  
repositioning text, 186  
Retrieve Dimensions command  
    on Drawing Annotation Panel, 180, 240  
Retrieve Dimensions dialog box, 180-181, 210, 240  
retrieving dimensions automatically, 236-237  
Review Questions  
    Chapter 1, 29  
    Chapter 2, 55  
    Chapter 3, 75  
    Chapter 4, 92  
    Chapter 5, 117  
    Chapter 6, 142  
    Chapter 7, 166  
    Chapter 8, 190  
    Chapter 9, 217  
    Chapter 10, 244  
    Chapter 11, 266  
    Chapter 12, 296  
    Chapter 13, 311  
    Chapter 14, 330  
Revolve command, 221, 225, 249  
Revolve dialog box, 225, 226, 249  
revolved feature, 221, 225-226, 349  
right-hand rule of part rotation, 282, 349  
right mouse button, functions of, 24  
rod guide design, 194  
Rod Guide.idw, 214  
Rod Guide.ipt, 205  
root, of binary tree, 60, 349  
Rotate command, on Inventor Standard toolbar, 22, 44-46  
Rotate Component command, on Assembly Panel, 300

rotation, dynamic, 44-46  
rotational degrees of freedom, 280, 349  
Rotation Axis button, of Circular Pattern dialog box, 231  
rough sketch, creating, 32  
round, 90, 350  
    3D, 256  
rows and columns, directions in rectangular array, 260  
rules for design intent, 78, 350

## S

saddle bracket file, 81-91  
Saddle Bracket.ipt, 82  
Save All command, 28  
Save As dialog box, 37  
Save Border command, 233  
Save button, on Inventor Standard toolbar, 36, 235  
Save command, 28, 36  
Save Title Block command, 234  
saving a model file, 28  
    periodically, 227  
    and sketch mode, 36  
Scale area, of Section View dialog box, 238  
scale of drawing view, adjusting, 178-179  
screen layout, 21-24  
screw, for press assembly, 303  
Screw.ipt, 303  
Sections box, in Loft dialog box, 253  
section view, 238, 350  
    dimensioning, 240  
    label for, 239  
Section View command, on Drawing Views Panel, 238  
Section View dialog box, 238  
Select Assembly dialog box, 308

- Select Component dialog box, 175, 176
- Select Dimensions button, in Retrieve Dimensions dialog box, 240
- Select View button
  - in Parts List dialog box, 320
  - in Retrieve Dimensions dialog box, 181
- self-intersecting geometric shapes, 32
- sequential record of construction steps, 78, 350
- settings, for constraints, 110
- setting the default sketch plane, 149
- Shaded Display button, on Inventor Standard toolbar, 46, 230
- shaded display mode, 46
- Shaded icon, in Drawing View dialog box, 179
- Shaft Support.iam, 279
- shape-before-size design philosophy, 31, 350
- Sheet Formats folder, in history tree, 175, 317
- Sheet Metal page, of Visual Syllabus, 26
- Shell command, on Part Features panel, 247, 257
- Shell dialog box, 257
- shelling, 257-258, 350
- Shift key
  - to select multiple features, 196
  - with Trim and Extend commands, 129
- Show All Constraints, 102
- Show Constraints, 98, 99, 101
- Show Dimensions command, 85, 187
- Size selection box, of Edit Sheet dialog box, 177
- sketch
  - guidelines for creating, 32
  - over-constrained, 104
  - proportional, 32
  - refining after extrusion, 137-139
  - rough, 32
  - under-constrained, 138
- Sketch button, in Inventor Standard toolbar, 37, 48
- sketch constraints, defaults for, 110
- sketch dimensions
  - modifying, 40, 65
  - repositioning, 65
- sketched features, 72, 350
- sketching a profile, 124-133
- sketch mode, 37
  - and saving a file, 36
- sketch plane, 47-48, 350
  - aligning, 48
  - with BORN technique, 148
  - default, setting, 149
  - as local coordinate system, 48
- Sketch tab, of Options dialog box, 110
- Smooth constraint, 100
- solid modeling, advancements in the 1980s, 59
- solid models, 18, 350
  - creating from profile, 136-137
  - downstream applications of, 171
  - shelling, 257-258
  - and 2D drawings, 171
- solid primitives, 18
- solids
  - composite, 59
  - primitive, 59
  - prismatic, 262
- spatial boundaries, in solid modeling, 18
- Standard (in).iam template, 277
- Standard (in).ipt template file, 21, 33, 63, 81, 98, 124, 149, 196, 223, 248
- status bar, 21, 24
  - command descriptions in, 33
  - coordinate readout in, 34
  - help in, 24
  - and number of constraints applied to geometry, 98
- steps in parametric part modeling, 31-32
- strategy for modeling, 61, 78
  - and parent/child relationships, 147
  - and pulley, 221-222
- Styles and Standards Editor dialog box, 173
  - General tab of, 173
  - Text tab of, 174
  - Units tab of, 174
- Styles Editor command, on Format pull-down menu, 173, 210
- subassemblies, 271, 350
- subtraction operation, 59
- support for Inventor, online, 26
- Suppress Features command, 162
- suppressing a feature, 162, 164
- surface models, 18, 350
- surfaces, in solid models, 18
- sweep, linear, 262
- Sweep command, on Part Features panel, 247, 264
- Sweep dialog box, 264
- sweeping, 262, 350
- sweep path, 262, 351
  - defining, 262
- sweep section, 262, 351
  - defining, 263

- swept feature, creating, 262-264
- symbols for geometric constraints, 35-36
- symmetrical design characteristics, 221
- symmetrical feature, 221, 220-245, 351
- Symmetric constraint, 100
- symmetry, 221, 351  
axis of, 221
- ## T
- Table Layout button, in Edit Parts List dialog box, 324
- tangent, 351
- Tangent assembly constraint, 281, 283
- Tangent assembly constraint symbol, 35
- Tangent constraint, 100, 108, 128
- taper angle, 40
- templates  
creating for drawing, 235  
for modeling tasks, 20-21
- Templates folder, 235
- terminal branches, 351  
of binary tree, 60
- termination surface, 83, 351
- text  
creating, 186  
repositioning, 186
- Text command, on Drawing Annotation Panel, 186, 215, 216
- Text tab, of Styles and Standards Editor dialog box, 174
- thickness, of shell, 257
- third-angle projection, 178, 179, 351
- Thread command, on Part Features panel, 276, 277, 303
- threads, 276-277  
creating with holes, 301-302
- Three point arc command, on 2D Sketch Panel, 155
- 3D Cartesian coordinate system, 47, 351
- three-dimensional computer models, 16
- 3D construction, advanced, 246-269
- 3D coordinate triad, 21, 23
- 3D fillets, 256
- 3D Rotate display, 44-45
- 3D rounds, 256
- 3D solid primitives, 18
- 3D views, working with, 42-46
- title block, 172, 352  
completing, 186  
defining new, 232  
saving, 234
- Title Block dialog box, 234
- Title Blocks folder, 206
- To Next option, in extrusion, 74, 88, 89
- toolbars  
Inventor Standard, 21, 22  
2D Sketch Panel, 22
- Tools pull-down menu, 110, 111  
Application Options command, 110, 149, 307  
Bill of Materials command, 328  
Document Settings command, 64
- tooltip, 33
- To option, in extrusion, 83
- top bar, for press assembly, 301-302
- Top Bar.ipt, 302
- top-down approach to assembly modeling, 272, 352
- tracking parent/child relationships, 147
- trail lines, 307, 310, 352
- Trail Origin button, in Tweak Component dialog box, 309
- trajectory, 262, 352
- transformation distance, in exploded assembly, 309
- Transformations area, of Tweak Component dialog box, 309
- translational degrees of freedom, 280, 352
- tree, CSG binary vs. model history, 78
- triad, 3D coordinate, 23
- triangular plate.ipt, 110
- Trim command, on 2D Sketch Panel, 129-130, 248
- tutorials for Inventor operations, 26
- Tweak Component dialog box, 308-311
- Tweak Components command, 308
- 2D Cartesian coordinate system, 352
- 2D drafting programs, 17  
limitations of, 17
- two-dimensional drawings  
creating, 172  
importance of, 171  
scaling, 172  
and solid models, 171
- 2D Fillet dialog box, 133, 249
- 2D sketch, proportional, 32
- 2D Sketch Panel, 21, 22, 37, 41  
Auto Dimension command, 106, 131  
Center point arc command, 155, 202

Center point circle command, 159, 163, 205  
 Extend command, 129-130  
 Fillet command, 90, 133, 197, 249  
 General Dimension command, 63, 153  
 Line command, 33  
 Offset command, 140  
 Parameters command, 115  
 Project Geometry command, 155, 159, 197  
 Rectangle command, 63  
 Show Constraints command, 98, 99, 101  
 Three point arc command, 155  
 Trim command, 129-130  
 Two point rectangle command, 73, 197  
 2D Sketch Panel toolbar, 22  
 Two point rectangle command, in 2D Sketch Panel, 73, 197  
 types of wireframe geometry, 122

## U

U-bracket.ipt, 165, 172, 175, 187, 188  
 U-bracket model, 148, 171  
 underconstraining features, 271  
 Undirected Angle solution, of Angle assembly constraint, 282  
 Undo command, 101  
 union operation, 59  
 units, selecting at file creation, 20  
 Units tab  
 of Document Settings dialog box, 64, 111-112

of Styles and Standards Editor dialog box, 174  
 Update button, on Inventor Standard toolbar, 187  
 Update command, 85-86  
 user coordinate systems (UCS), 48, 352  
 user parameters, 352  
 variables, feature control, 111

## V

Vertical constraint, 100, 102  
 Vertical constraint symbol, 35  
 view  
 isometric, 42-43  
 3D, 42-46  
 viewing parametric relations, 115-116  
 View pull-down menu, 40, 42  
 Degrees of Freedom, 280  
 Isometric command, 43  
 Object Visibility command, 199  
 Previous View command, 43  
 Zoom All command, 40  
 view-related commands, 22  
 views, repositioning, 179-180  
 view scale, adjusting, 178-179  
 visibility  
 of reference planes, 187  
 toggling, 150, 196

## W

What to Do area, of Open dialog box, 20  
 Window pull-down menu, Cascade command, 172  
 Wireframe Display, on Inventor Standard toolbar, 155, 198, 205, 251

Wireframe Display button, on Inventor Standard toolbar, 46  
 wireframe display mode, 46  
 wireframe geometry, 122  
 wireframe models, 17, 353  
 work axes, 150, 353  
 turning on and off, 199  
 work features, 194, 353  
 default, 150  
 Work Plane command, 198, 250, 204  
 work planes, 150, 353  
 angled, 198-199  
 for lofting, 250  
 offset, 204  
 world coordinate system, 47, 353  
 XY plane of, 48  
 world space, 47

## X

X axis, 47, 150, 353  
 XY plane, 150, 155, 353  
 as default sketch plane, 149  
 of world coordinate system, 48  
 XZ plane, 150, 151, 196, 353

## Y

Y axis, 47, 150, 353  
 YZ plane, 150, 353

## Z

Z axis, 47, 150, 353  
 Z button, in Tweak Component dialog box, 309  
 zoom, 24, 353  
 Zoom All, command, 40  
 Zoom button, on Inventor Standard toolbar, 43  
 Zoom command, 22, 43